Megapixel AHD CAMERA **User Manual**



1. Main Parts & Accessories










Assorted screw(3pcs)

2. Size








3. NOTES

- (1) Do not drop and prevent the camera from strong knocking.
- (2) Check and confirm the availability of right power supply. Wrong voltage will inflict damage to component(s) in camera.
- (3) Avoid focusing on the strong light(sunshine, light etc)
- (4) Do not use camera in overheated and humid environment. Keep a good ventilation so as to reduce fire and damp.
- (5) Do not touch the lens directly, please use the clean cloth with alcohol to wipe the dust if
- (6) Only the professional technicians are entitled for installation and repair. By no means. this camera shall not be repaired or dismantled on customer's own. Manufacturer holds no responsibility in case of unauthorized repair, and use of uncertified space parts.

4. Connection Diagram




5.Installation








Installation Steps C





Installation Steps E.



6. Technical Parameters

Model .	AHD 1.3Megapixel
Image Sensor	1/3 COMS 1.3Megapixel
Effective Resolution	1280 (H) +960 (V)
TV System .	PAL:NTSC(OSD menu transition)
Effective Pixel	1. 3Megapixel
Minimum Illumination	Color (I.01Lux;IR ON 0 Lux
S.N. Ratio	≥69dB (AGC OFF)
Day & Night Mode	External control(default)/automatic color/ black and white/(OSD Transition) with IR-CUT switch
Auto Gain Control	AUTO
Back Light Comp	AUTO :
White Banlance	AUTO
Digital Noise Reduction	3D
WDR	Digital WDR
Lens .	1.56mm Megapixel lens
Angle of view	ceiling mount 360 wall mount 180
Electronic Shutter	AUTO 1/50 (1/60) -1 (100, 000Sec)
Video Oul	AHD VIDEO (960P)
IR Leds Qly	# 5 IR leds for 23 PCS
IR Distance	10 · · 15M ·
Motion Detection	Square tracking and four areas set the location and size
Occupied ratio for video recording	1H~990MB
OSD Languages	support 12 different languages English/Chinese-Simple/Chinese- Traditional German-French Italian Spanish: Polish Russian Portuguese, Dutch: Turkish
Press OSD "down"Key for 5 seconds	PAL switch to NTSC (PAL default)
Press OSD "L"Key for 5 seconds	Signal output /AHD swicth to CVBS(AHD default)
Press OSD "R"Key for 5 seconds	Signal output /AHD swicth to CVBS
Passing through fog	YES .
Ingress Protection	IP65
Operating Temperature	-20° C '-70° C
Power Supply .	DC12V±10%
Power Consumption	≤5W
Size	150+46
Wight	bare camera 422g, with package 640g